

Bruun Inspektion A/S hereby certify that the quality management system of:
HMK Bilcon A/S, Hadsundvej 295, 9260 Gistrup

has been assessed and registered by Bruun Inspektion A / S in accordance with the requirements of the following international standard:

ISO 3834-2:2021

The quality management system applies to the scope:

Fusion welding of metallic materials.

See Appendix I.

Valid from: 04-09-2026
Valid start date

Nr. Nebel, Danmark
Place of issue of certificate

Expires: 03-09-2031
The certificate is valid until to

Issued first time: 09-06-2023
Date of start of validity of certificate



UNDERSKRIFT

Gitte Bruun

This certificate is valid, on condition of satisfactory completion of annual audits.

Certificate ID: 20260810/168 , Subject ID: 90000325295

Check, if necessary, the validity of this certificate by contacting Bruun Inspektion A/S

Appendix 1.

Material group: 22 og 23 according to CEN ISO /TR 15608:2017.

Manufacture according to the following standards: EN 13445, EN 13480 .

Weldingproces: 131 og 141 Regarding EN ISO 4063:2023.

Weldingcoordinator (C,S,B): Jørgen Brogaard Esbensen . S



Vadgårdsvej 25, 6830 Nr. Nebel



Info@bruun-inspektion.dk



+45 88 27 27 27